

# Kapalua Schematic

REV : X02

BDQ11/LA1601 Schematic with Capture CIS and Function field  
uFCPGA Banias  
12-27-2002  
REV: 0.4


@ : Depop Component
1@ : Depop Component
2@ : Pop Component

DELL CONFIDENTIAL/PROPRIETARY

Compal Electronics, Inc.

Title		
Cover Sheet		
Size	Document Number	Rev
	BDQ11/LA-1601	0.4
Date:	星期五, 十二月 27, 2002	Sheet 1 of 56

# Block Diagram



**PM TABLE**


power plane State	+3VALW +5VALW	+3VSUS +5VSUS +2.5V_MEM +1.5VSUS	+5VRUN +3VRUN +1.8VRUN +1.5VRUN +1.2VRUN +VCC_CORE +VCCP +12V
S0	ON	ON	ON
S1	ON	ON	ON
S3	ON	ON	OFF
S5 S4/AC	ON	OFF	OFF
S5 S4/AC don't exist	OFF	OFF	OFF


**PCI TABLE**



PCI DEVICE	IDSEL	REQ#/GNT#	PIRQ
CARD BUS	AD17	1	D,C
LAN	AD16	4	C
DOCK	AD24	0	B
MINI PCI	AD19	3	D,B(NP)
VGA			A,B(NP)

**USB TABLE**


USB PORT#	DESTINATION
0	BACK
1	BLUETOOTH
2	BACK
3	DOG
4	MOD
5	DOCK








**Place near each pin  
W>40 mil**




**W=20 mils**




**CK408**


Rev 1.1



**Please closely pin42**



**Place crystal within  
500 mils of CK408**









**Place near CK408**

S2	S1	S0	CPU	3V66[0..4]	3V66_5/66IN
1	0	0	66	66IN	66 Input
1	0	1	100	66IN	66 Input
1	1	0	200	66IN	66 Input
1	1	1	133	66IN	66 Input
0	0	0	66	66	66 Input
0	0	1	100	66	66 Input
0	1	0	200	66	66 Input
0	1	1	133	66	66 Input
Mid	0	0	Hi-z	Hi-z	Hi-z
Mid	0	1	TCLK/2	TCLK/2	TCLK/2
Mid	1	0	Reserve	Reserve	Reserve
Mid	1	1	Reserve	Reserve	Reserve

















**DELL CONFIDENTIAL/PROPRIETARY**  
**Compal Electronics, Inc.**

File		CPU Bypass	
Size	Document Number	Rev	
C	B0Q11LA-1601	0.4	
Date:	星期二, 十二月 27, 2002	Sheet	9 of 56











DELL CONFIDENTIAL/PROPRIETARY  
Compal Electronics, Inc.

### FAN1 Control and Tachometer




### CPU Temperature Sensor




11 DDR\_D[0..63] <<>>   
 11 DDR\_CB[0..7] <<>>   
 11 DDR\_DS[0..8] <<>> 


**Layout Note:**  
Place these resistor closely DIMM0, all trace length < 750 mil






**Layout Note:**  
Place these resistor closely DIMM0, all trace length Max=1.3"



**Layout Note:**  
Place these resistor closely DIMM0, all trace length < 750 mil



6,15,19,31 ICH\_SMBDATA <<>>   
 6,15,19,31 ICH\_SMBCLK <<>> 



**DELL CONFIDENTIAL/PROPRIETARY**  
**Compal Electronics, Inc.**



Title			
DDR-SODIMM SLOT1			
Size	Document Number	Rev	
	BDDQ11/LA-1601	0.4	
Date:	星期五, 十二月 27, 2002	Sheet	14 of 56






10 G\_AD[0..31] <<>>  
 10 G\_C/BE#[0..3] <<>>  
 10 G\_SBA[0..7] <<>>

6 CK\_66M\_AGP <<>> CK\_66M\_AGP  
 10 G\_REQ# <<>> G\_REQ#  
 10 G\_ST0 <<>> G\_ST0  
 10 G\_ST1 <<>> G\_ST1  
 10 G\_ST2 <<>> G\_ST2



ST1	ST2	
X	1	DDR
0	X	TEST
1	X	400 Mhz BPSB



10 G\_AD\_STB0 <<>> G\_AD\_STB0  
 10 G\_AD\_STB0# <<>> G\_AD\_STB0#  
 10 G\_AD\_STB1 <<>> G\_AD\_STB1  
 10 G\_AD\_STB1# <<>> G\_AD\_STB1#  
 10 G\_SB\_STB <<>> G\_SB\_STB  
 10 G\_SB\_STB# <<>> G\_SB\_STB#

10 G\_FRAME# <<>> G\_FRAME#  
 10 G\_DEVSEL# <<>> G\_DEVSEL#  
 10 G\_IRDY# <<>> G\_IRDY#  
 10 G\_TRDY# <<>> G\_TRDY#  
 10 G\_STOP# <<>> G\_STOP#  
 10 G\_PAR <<>> G\_PAR  
 10 G\_REQ# <<>> G\_REQ#  
 10 G\_GNT# <<>> G\_GNT#  
 10 G\_PIPE# <<>> G\_PIPE#

17.33 TV\_Y <<>> TV\_Y  
 17.33 TV\_C <<>> TV\_C  
 17.33 TV\_CVBS <<>> TV\_CVBS

17.33 DAT\_DDC2 <<>> DAT\_DDC2  
 17.33 CLK\_DDC2 <<>> CLK\_DDC2  
 17.33 HSYNC <<>> HSYNC  
 17.33 VGA\_RED <<>> VGA\_RED  
 17.33 VGA\_GRN <<>> VGA\_GRN  
 17.33 VGA\_BLU <<>> VGA\_BLU



33 DVI\_TX0+ <<>> DVI\_TX0+  
 33 DVI\_TX0- <<>> DVI\_TX0-  
 33 DVI\_TX1+ <<>> DVI\_TX1+  
 33 DVI\_TX1- <<>> DVI\_TX1-  
 33 DVI\_TX2+ <<>> DVI\_TX2+  
 33 DVI\_TX2- <<>> DVI\_TX2-  
 33 DVI\_TX3+ <<>> DVI\_TX3+  
 33 DVI\_TX3- <<>> DVI\_TX3-

AGP8X\_DET CG  
 AGP8X\_DET GC  
 PCI\_PIOB# <<>> PCI\_PIOB#  
 CK\_66M\_AGP  
 G\_REQ#  
 G\_ST0  
 G\_ST2  
 G\_SB\_STB  
 G\_SB\_STB#  
 G\_SBA2  
 G\_SBA4  
 G\_SBA6  
 RUNPWROK <<>> RUNPWROK

G\_IRDY#  
 G\_TRDY#  
 G\_STOP#  
 G\_C/BE#3  
 G\_AD31  
 G\_AD29  
 G\_AD\_STB1#  
 G\_AD\_STB1  
 G\_AD27  
 G\_AD25  
 G\_C/BE#2  
 G\_AD21  
 G\_AD19  
 DBI\_HI  
 DBI\_LO  
 G\_AGPBUSY#  
 VREFCG <<>> VREFCG  
 G\_AD15  
 G\_AD13  
 G\_AD11  
 G\_AD9  
 G\_AD7  
 G\_AD\_STB0#  
 G\_AD\_STB0  
 G\_AD5  
 G\_AD3  
 G\_AD1  
 VSYNC  
 HSYNC  
 VGA\_RED  
 VGA\_GRN  
 VGA\_BLU  
 TV\_Y  
 TV\_C  
 TV\_CVBS  
 TVDAC4  
 ICH\_SUS\_STAT# <<>> ICH\_SUS\_STAT#

35,38,44,45,47 RUNPWROK +1.5VRUN  
 T250 PAD  
 T25 PAD  
 T252 PAD  
 T276 PAD  
 C123 0.1U\_0402\_16V4Z-L  
 C508 0.047U\_0402\_16V4M-L  
 C506 0.047U\_0402\_16V4M-L  
 C511 0.1U\_0603\_25V7M-L  
 C186 0.1U\_0603\_25V7M-L  
 C508 0.1U\_0603\_25V7M-L  
 C484 0.1U\_0603\_25V7M-L

33 DVI\_TX4+ <<>> DVI\_TX4+  
 33 DVI\_TX4- <<>> DVI\_TX4-  
 33 DVI\_TX5+ <<>> DVI\_TX5+  
 33 DVI\_TX5- <<>> DVI\_TX5-  
 33 DVI\_CLK+ <<>> DVI\_CLK+  
 33 DVI\_CLK- <<>> DVI\_CLK-  
 33 DVI\_SCLK <<>> DVI\_SCLK  
 33 DVI\_SDAT <<>> DVI\_SDAT  
 DVI\_DETECT <<>> DVI\_DETECT  
 +3VRUN  
 PCI\_PIOA# <<>> PCI\_PIOA#  
 PCI\_PIOA# 18  
 FAN2\_TACH\_FB <<>> FAN2\_TACH\_FB 13  
 FAN2\_5V <<>> FAN2\_5V 13  
 +1.5VRUN  
 G\_SBA0  
 G\_SBA1  
 G\_SBA3  
 G\_SBA5  
 G\_SBA7  
 G\_DEVSEL#  
 AGP\_RST#  
 G\_PIPE#  
 G\_RBF# <<>> G\_RBF# 10  
 G\_WBF# <<>> G\_WBF# 10  
 G\_AD30  
 G\_AD28  
 G\_AD26  
 G\_AD24  
 G\_AD22  
 G\_AD20  
 G\_AD18  
 G\_AD23  
 G\_AD17  
 G\_AD16  
 DBI\_LO  
 G\_AGPBUSY# <<>> G\_AGPBUSY# 20  
 VREFCG R 1 <<>> VREFCG 10  
 G\_C/BE#1  
 G\_AD14  
 G\_AD12  
 G\_AD10  
 G\_AD8  
 G\_AD6  
 G\_AD4  
 G\_AD2  
 G\_AD0  
 G\_C/BE#0  
 G\_PAR  
 G\_GNT#  
 +1.5VRUN  
 GC\_BL\_SUSPEND <<>> GC\_BL\_SUSPEND 34  
 STP\_AGP R# <<>> STP\_AGP R# 20  
 +3VSUS  
 M\_SEN# <<>> M\_SEN# 17.33  
 DAT\_DDC2 <<>> DAT\_DDC2  
 CLK\_DDC2 <<>> CLK\_DDC2  
 M\_ID2# <<>> M\_ID2# 17  
 SBAT\_SMBDAT <<>> SBAT\_SMBDAT 35.43  
 SBAT\_SMBCLK <<>> SBAT\_SMBCLK 35.43  
 +3VRUN  
 +5VALW  
 FPVCC <<>> FPVCC  
 G\_PWR\_SRC  
 FOX\_Q10200A-6120L-U





Shielding Ground Pin  
 9,10  
 33,34  
 59,60  
 87,88  
 113,114  
 141,142  
 167,168  
 191,192


Compal Electronics, Inc.		
VGA Daughter Board		
BDQ11/LA-1601		
Size	Document Number	Rev
		0.4
Date:	星期五, 十二月 27, 2002	Sheet 16 of 56




DELL CONFIDENTIAL/PROPRIETARY







Evaluate Package










BID3	BID2	BID1	BID0	REV
0	0	0	0	X00
0	0	0	1	X01
0	0	1	0	X02








**STAC9750**

8/12 Changed by  
Dell's Require  
12/18 Item 75

**DELL CONFIDENTIAL/PROPRIETARY**  
Compal Electronics, Inc.




Title			AC97		
Size	Document Number			Rev	0.4
BDQ11/LA-1601					
Date:	星期五, 十二月 27, 2002	Sheet	23	of	56




GAIN0	GAIN1	AV
0	0	6dB
0	1	10dB
1	0	15.6dB
1	1	21.6dB




PLACE CHOKE  
NEAR  
CONNECTOR





USB PORT#	DESTINATION
0	BACK
1	BT
2	BACK
3	DOG
4	MOD
5	DOCK








10/17  
10/29  
change to C  
12/04  
Changed Package



TOP view








**DELL CONFIDENTIAL/PROPRIETARY**  
**Compal Electronics, Inc.**

**LAN TRANSFORMER**








Title		Rev	
Size		Document Number	
Date:		BDDQ11/LA-1601	
Date:		Rev 0.4	

Date: 星期五, 十二月 27, 2002  
 Sheet 28 of 56



**DELL CONFIDENTIAL/PROPRIETARY**  
**Compal Electronics, Inc.**


Title			PCMCIA Controller		
Size	Document Number	Rev		0.4	
BDQ11/LA-1601					
Date:	星期五, 十二月 27, 2002	Sheet	29	of	56



SHDN#	VPPD1	VPPD0	CBS_VPP
1	0	0	
1	0	1	
1	1	0	
1	1	1	
0	X	X	

SHDN#	VCCD1#	VCCD0#	CBS_VCC
1	0	0	
1	0	1	
1	1	0	
1	1	1	
0	X	X	



**DELL CONFIDENTIAL/PROPRIETARY**  
**Compal Electronics, Inc.**


**CardBus Socket**

**BDQ11/LA-1601**


Title: \_\_\_\_\_  
 Size: \_\_\_\_\_ Document Number: \_\_\_\_\_ Rev: 0.4  
 Date: 星期五, 十二月 27, 2002 Sheet 30 of 56















PLACE TERMINATIONS CLOSE TO DOCK CONNECTOR




















SUB\_6782U  
SMbus address A2




Keep no noise coupled,  
Especially the TP\_GND



# Parallel Port





**POWER SEQUENCING**

**HYST:**  
VCC for 10 degree  
GND for 2 degree



MAX6509 goes in CPU cavity.  
Discretes go outside.

**SET-HOT Vrsion**



Thermistor goes in CPU cavity.  
Dell P/N 8K573  
Semitech P/N 103KT2125-1P






10/24 pop those item  
11/8 change back

10/24 de-pop those item  
11/8 change back






10/25 Item68




















**Fiducial Mark**




11/27  
For Cost-BOM




Z-series AC Adaptor Connector




Old Low-Power Adapter Detection



TRACE →  
THE POINT →







TRACE →  
THE POINT →




SUYIN\_20175A-09G1  
TOP view

+1.2VRUN/+1.8VRUN SOURCE



Allows SUS planes to power ALW planes when possible




THIS SHEET OF ENGINEERING DRAWING IS THE PROPRIETARY PROPERTY OF COMPAL ELECTRONICS, INC. AND CONTAINS CONFIDENTIAL AND TRADE SECRET INFORMATION. THIS SHEET MAY NOT BE TRANSFERRED FROM THE CUSTODY OF THE COMPETENT DIVISION OF R&D DEPARTMENT EXCEPT AS AUTHORIZED BY COMPAL ELECTRONICS, INC. NEITHER THIS SHEET NOR THE INFORMATION IT CONTAINS MAY BE USED BY OR DISCLOSED TO ANY THIRD PARTY WITHOUT PRIOR WRITTEN CONSENT OF COMPAL ELECTRONICS, INC.

DA0JM2MBCA1  
Dell-Compal Confidential

DELL CONFIDENTIAL/PROPRIETARY			
COMPAL ELECTRONICS, INC			
Title	+1.2V & +1.8V		
Size	Document Number	BDQ11/LA-1601	Rev 0.4
Date	2002年12月27日	Sheet 44	of 56


+1.5VSUS/+1.05V (+VCCP)



DELL CONFIDENTIAL/PROPRIETARY

COMPAL ELECTRONICS, INC	
File	
+1.5V & +1.05V	
Size	Document Number
	BQD11/LA-1601
Date: 2002.11.27	Sheet 45 of 56


THIS SHEET OF ENGINEERING DRAWING IS THE PROPRIETARY PROPERTY OF COMPAL ELECTRONICS, INC. AND CONTAINS CONFIDENTIAL AND TRADE SECRET INFORMATION. THIS SHEET MAY NOT BE TRANSFERRED FROM THE CUSTODY OF THE COMPETENT DIVISION OF DEPARTMENT EXCEPT AS AUTHORIZED BY COMPAL ELECTRONICS, INC. NEITHER THIS SHEET NOR THE INFORMATION IT CONTAINS MAY BE USED BY OR DISCLOSED TO ANY THIRD PARTY WITHOUT PRIOR WRITTEN CONSENT OF COMPAL ELECTRONICS, INC.




**+2.5V/+1.25V**

DDR Termination Voltage

09/26 By  
Dell's  
Request



DELL CONFIDENTIAL/PROPRIETARY		
Compal Electronics, Inc.		
File	1.25V/2.5V	
Size	Document Number	Rev
	BDQ11/LA-1601	0.4
Date:	星期二, 十一月 27, 2002	Sheet 46 of 56



value provided  
1.04% offset;  
old value was  
for old 2.67%  
offset.

BG waveforms  
improved, may  
delete from  
future  
revision.


Set up for  
constant-ripple  
mode. Was  
constant frequency  
mode.




20 mil Trace list for layout  
The +5VRLUN (PIN38  
AND PIN20)  
BST1\_VCORE  
BST2\_VCORE

V I D							Vcore
VID 5	VID 4	VID 3	VID 2	VID 1	VID 0	V	
0	1	0	1	1	1	1.340	
0	1	1	0	0	0	1.324	
0	1	1	0	1	0	1.292	
0	1	1	1	0	0	1.260	
0	1	1	1	0	1	1.244	

100 mil Trace list for layout


- DH\_VCORE
- LX\_VCORE
- DL\_VCORE
- DH\_VCORE2
- LX\_VCORE2
- DL\_VCORE2






+5VSUS Source





	65W ( 2.93A )	90W ( 4.0A )	130W ( 5.85A )
65W	H	L	L
AC_130W_90W	H	L	H



12/16 Change by Dell

For long-term solution

+DC\_IN discharge path

<b>DELL CONFIDENTIAL/PROPRIETARY</b>			
<b>Compal Electronics, Inc.</b>			
<b>CHARGER</b>			
<b>BDQ11/LA-1601</b>			Rev 0.4
Date:	星期五, 十二月 27, 2002	Sheet	50 of 56

# Version Change List (P. I. R. List)

Item	Page#	Title	Date	Request Owner	Issue Description	Solution Description	Rev.
1	27	Ethernet	8/18/2002	Dell	R318 use the same value as Lindbergh	R318 change the value from 1240Ω to 1140Ω	X00
2	27	Ethernet	8/18/2002	Dell	Netname change for A-2 chip	Change netname from 4401_CLOCKRUN to 7705M_CLOCKRUN	X00
3	27	Ethernet	8/18/2002	Dell	Populate R549 for 5705m controller	5702 controller do not need to change	X00
4	27	Ethernet	8/18/2002	Dell	Delete "POP SMBUS ISOLATION FOR 5702" text	Delete text	X00
5	28	LAN Transformer	8/18/2002	Dell	No need for RN1 pins 1,2,3,4 to ground connection	Delete RN1 pins 1,2,3,4 to ground connection	X00
6	28	LAN Transformer	8/18/2002	Dell	Delete the net name LIN_1000# and rename net of Pin G12 of U1A, Page 27, to DOCK_LED_1000#	Delete the net name LIN_1000#, rename net of Pin G12 of U1A to DOCK_LED_1000#	X00
7	8	Banias Processor	8/20/2002	Dell	PJP11 & PJP16 text discribe error	Change PJP11 to Short, and PJP16 to Open.	X00
8	27	Ethernet	8/20/2002	Dell	So for now we can use 1150 Ohm 1% resistor for R318 and we will continue with the 5702 controller	R318 change the value from 1140Ω to 1150Ω	X00
9	31	MINI PCI	8/20/2002	Dell	Change pin 17 of JPCI from PCI_PIRQB#to PCI_PIRQD#	Change pin 17 of JPCI connection to PCI_PIRQD#	X00
10	42	Power DC-IN	8/20/2002	Dell	Change PQ32, PR73, PR74, PR77 to NP	Updated PQ32, PR73, PR74, PR77 to NP	X00
11	1	Cover page	8/22/2002	Dell	On the title page place the name of the project Kapalua	Updated Schematic cover page text	X00
12	27	Ethernet	8/23/2002	Dell	Changed netname from 7705M_CLOCKRUN to 5705M_CLOCKRUN	Updated netname from 7705M_CLOCKRUN to 5705M_CLOCKRUN	X00
13	28	LAN Transformer	8/23/2002	Dell	Add 0Ω (0402 resistors) resistors to LAN_TX0-/LAN_TX0+, LAN_RX1-, LAN_RX1+, LAN_TX2-, LAN_TX2+, LAN_TX3-, LAN_TX3+	Add R776, R777, R778, R779, R780, R781, R782 and R783	X00
14	40	Power Control	8/29/2002	Dell	Using wrong Control signal of 1.8V rail drain on Q85.2	change the control signal of 1.8V rail drain from RUN_ON# to RUN_ON	X00
15	44	1.8V / 1.2V	8/29/2002	Compal	Change the control signal of 1.2VRUN from RUN_ON to RUNPWROK	Add PR766 connect to RUNPWROK, and reserved PR720 to NP	X00
16	47	Vcc_core	9/03/2002	Dell	Banias update PBOOT voltage spec with 1.2V	change PR755 to 16.5K and PR757 to 15K	X00
17	40	Power Control	9/04/2002	Compal	System doesn't work in using battery only	change R606 value from 470K to 200K	X00
18	40	Power Control	9/04/2002	Compal	Reduce +3VSUS power rail up response time and solve unexpected step waveform	Depoplate C680	X00
19	16	VGA Board	9/04/2002	Compal	VGA no reference voltage detected	Poplate R124	X00
20	45	1.5V / 1.05V	9/05/2002	Compal	SUSPWROK_1P5V control signal detected glitch issue	Add PR767 and reserved PR742 to NP	X00
21	46	1.25V / 2.5V	9/05/2002	Compal	SUSPWROK_1P5V control signal detected glitch issue	Add PR768 and reserved PR605 to NP	X00
22	40	Power Control	9/26/2002	Dell	Fixes the 3VSRV to 3VRUN leakage problem	Change R603 to 22Ω	X01
23	40	Power Control	9/26/2002	Dell	We need a Soft Start feature	Add C680 to 0.1uF	X01
24	20	ICH4-M	9/26/2002	Dell	Change Board Rev resistor to X01	Depopp R287, and Pop R286	X01
25	45	1.5V / 1.05V	9/26/2002	Dell	Add 0 ohm resistor at PU18 pin 15 and pin 16	Add PR769 and PR770 to 0Ω	X01
26	46	1.25V / 2.5V	9/26/2002	Dell	Add a 0 Ohm resistor at PU11 pin 15	Add PR771 to 0Ω	X01

<b>Compal Electronics, Inc.</b>			
<b>Changed-List History</b>			
Size	Document Number	Rev	
	<b>BDQ11/LA-1601</b>	0.4	
Date:	星期五, 十二月 27, 2002	Sheet	51 of 56

# Version Change List (P. I. R. List)

Item	Page#	Title	Date	Request Owner	Issue Description	Solution Description	Rev.
27	28	NIC high po issue	10/17/2002	DELL	High po test fail because RN1 pitch too close	change RN1 to R785~r788 to enlarge the pitch	X01
28	26	Add PD for BT	10/17/2002	DELL	leverage from LK	Add R789 10K PD to COEX1_BT_ACTIVE	X01
29	25	Dog h power rating	10/17/2002	Compal	The current rating of MOS and Bead is too small in Dog house	change Q1,F1,F2,L25 part to meet Doghouse power current requirement (F1&F2 create new symbol now)	X01
30	13	Fan soft start	10/17/2002	Compal	No soft start will cause +5VRUN droop low	change C127 and C110 pop(don't do it per Bo's command)	X01
31	22	cd audio pull down	10/18/2002	Compal	when we don't plug in CDrom, audio trace will floating	add R, R to tie the INT_CD_L/R ground	X01
32	22	reserve series ATA	10/18/2002	DELL	change some power/gnd to NC for reserve series ATA interface for module bay	change JMODipin8,10,14,16,9,11, to NC,conecct SATA_DET# to pin13	X01
33	20,22,34	add SATA detect	10/18/2002	DELL	Add series ATA detect in module bay	Add net sdat_det# from module bay to EC and remove original sio_lid_ec#	X01
34	31	change MINI PCI pin NC	10/18/2002	DELL	change MINI-PCI pin NC (No use)	Change JPCI pin109 and pin 123 to NC and remove R457,C576	X01
35	22	cr_ref return cap.	10/18/2002	DELL	add a pull down cap. for cd_ref near JMOD	Add C from CD_REF to gnd near JMOD and let it unpop	X01
36	29	Reserve PCMCIA suspend pin	10/18/2002	DELL	Reserve PCMCIA suspend pin not use	depop D11 and reserve it for TI_SUSPEND#	X01
37	40	Power Q-SW	10/18/2002	DELL	Lindberg change Q12,Q55,Q77 to big rating, we will wait the EA report and make a decision	TBD	X01
38	38	Add 1.8V PWRGD	10/18/2002	DELL	Add the 1.8V power good to power sequence	change the U12 pin 13 from RUN_ON to 1P8V_PWRGD	X01
40	25,34	change DH enable	10/22/2002	DELL	change dog house power enable pin independent	Add R and R seprate the control signal of DH	X01
41	10	change to normal part	10/22/2002	Compal	change to vender normal specification part	change C743 and C744 from 50V to 16V rating	X01
42	31	remove pin of MINI-PCI	10/24/2002	DELL	change pin def. of MINI-PCI	romove pin 118, 120 ground for JPCI	X01
43	42	remove some PS_ID	10/24/2002	DELL	remove some reserve PS_ID component	Remove PQ32, PR77, PR74, PR73	X01
44	26,31	duplicate pull down	10/24/2002	DELL	remove duplicate pull down	Remove R789 , only use R767	X01
45	29	remove not use part	10/24/2002	DELL	remove the reserve part for carrbus controller	Delete R185	X01
46	38	change the thermaltrip	10/24/2002	DELL	change the thermal shut down solution from MAX to discrete	del U6, R30, R24, add U2, C29, R28, R20~R23, C27, R53, C65	X01
47	28	ESD Safty issue	10/24/2002	Compal	JPH_RJ layout change connection from GND to NC.	JPH_RJ pin 6 change connection from GND to NC.	X01
48	40	+3VRUN, +3VSUS FET ISSUE	10/25/2002	DELL	+3VSUS AND +3VRUN POWER RAIL MOSFET PARTS CHANGED	Q12 AND Q77 CHANGE PARTS FROM SI3456 TO SI4810	X01
49	33	RGB Beads value changed	10/25/2002	DELL	Using 0Ω instead of beads	Change the value of L101, L102, L103, L14, L15, L16, L17, L18	X01
50	33	Rev. changed	10/25/2002	Compal	PI3L301A revision change to PI3L301BA	U30 Rev. changed	X01
51	25	Dog House	10/29/2002	DELL	Must Design as Lindberg	R25 changed value to 100K and R26 (10K) change to C940 (0.022u_0805)	X01
52	9,12,15	Bulk Cap.	10/29/2002	Compal	Height Restriction	Changed Height limit of C933,C934,C731,C779,C788,C789 to 1.9mm	X01
53	9	CPU Bypass	10/29/2002	DELL	Changed Voltage Limit of Bulk Cap. to 2V	C671~C675,C678 Changed Voltage Limit to 2V	X01

<b>Compal Electronics, Inc.</b>			
<b>Changed-List History</b>			
Size	Document Number	Rev	
	<b>BDQ11/LA-1601</b>	0.4	
Date:	星期五, 十二月 27, 2002	Sheet	52 of 56

# Version Change List (P. I. R. List)

Item	Page#	Title	Date	Request Owner	Issue Description	Solution Description	Rev.
54	41	PAD & ME Parts	10/30/2002	Compal	Need to BLOW OUT 2.5mm Radius from Vias used to transition Tip and Ring from InnerLayer 4 to Bottom layer	Deleted H43 to meet 2.5mm Radius gap	X01
55	28	Magnetic & RJ45	10/30/2002	DELL	LAN Analog Switch ( PI3L301BA ) serial Resistors change type to Inductors	R776~R783 changed value from 0Ω to 15nH Inductor ( TDK MLK1005S15NJ )	X01
56	27	POP option to 5705	11/08/2002	Compal	change the POP option from 5702 to 5705	Depop L66, C344, C324 Pop R217, R549	X01
57	38	Thermal shut down to 6509	11/08/2002	DELL	change the thermal shut down solution from discrete to MAX	Add U6, R30, R24 Depop U2, C29, R28, R20~R23, C27, R53, C65	X01
58	27	LOM	11/27/2002	Compal	Depop dummy parts	Depop R388 (10K_0402) and C390 (0.01U_0402)	X02
59	41	PAD, ME, SPARE PARTS	11/27/2002	Compal	Add Cost-BOM parts	Add Z1(Switch-FPC), Z2(Touch_pad-FPC), Z3(MDC-Cable), Z4(Spk-mODULE), Z5(BT_Cable).	X02
60	9	Vcore Bypass CAP.	11/29/2002	Compal	Vcore by pass capacitors adjust for cost	Add C941~C944 (220UF_2V) Depop C671~C675, C678 (220UF_2V)	X02
61	40	Power Control	11/29/2002	Compal	package change for increase voltage tolerance	C680 changed package from 0402 to 0603	X02
62	20	ICH4	12/02/2002	Compal	Depop dummy part	Depop R529 (10K_0402)	X02
63	25	Dog House	12/04/2002	Compal	package change for component easy to buy	C940 changed package from 0805 to 0603	X02
64	30	Smart Card	12/11/2002	DELL	Need to implement 5 Smart Card changes.	Add R12, R26, C184, C189, Change C171 value from 390P to 470P	X02
65	27	BCM5705 By Pass	12/11/2002	DELL	Need to change package from 0805(4.7UF) to 1206(10UF) for cost	C339, C346, C352, C355, C393, C662, C368, C342	X02
66	All Pages	Page Symbol	12/13/2002	DELL	Put "DELL CONFIDENTIAL/PROPRIETARY" on Schematics	DELL CONFIDENTIAL/PROPRIETARY	X02
67	20	ICH4	12/13/2002	Compal	Delay Thermtrip to ICH4 so Intruder have time to get latch	Add C46 (0.1UF_0402)	X02
68	38	Thermtrip	12/17/2002	DELL	For Charger Selector Used (SIO_THERM_PWRDN net changed to SBAT_LOW)	Delete R206 & Q22	X02
69	27	BCM5705	12/17/2002	DELL	Delete 4401 Components	Delete U43, R388, C390, R367, R368	X02
70	28	LAN Transformer	12/17/2002	DELL	Delete 4401 Components	Delete R551 ~ R554	X02
71	28	LAN Transformer	12/18/2002	DELL	Changed Spec 2KV to 3KV	C1	X02
72	17	TV OUT	12/18/2002	DELL	Depop C14 for Cost	Depop C14	X02
73	33	DOCKING CONN.	12/18/2002	DELL	Remove RGB Bead	Delete L101, L102, L103, L14 ~ L18 & Trace	X02
74	23	AC_97 CODEC	12/18/2002	Compal	Added Resistors for TPS793475 LDO	Add R792, R793 (@)	X02
75	23	AC_97 CODEC	12/18/2002	DELL	Change the Value from 0 ohm to 1UF_0805	C636	X02
76	17	TV OUT	12/18/2002	DELL	Change RGB Bead Value & Package	Changed L5, L104, L105	X02
77	35	SIO	12/18/2002	Compal	ESD Cap is Needed on Reset to McCallen	Add D74 for ESD (@)	X02
78	30	Smart Card	12/19/2002	DELL	Added Cap (4.7uF_0805) for SCR_VCC_C to Depop	Add C945 for depop (@)	X02
79	17	TV OUT	12/19/2002	Compal	Depop C10, C11, C661 for RGB Signals	Depop C10, C11, C661(@)	X02

<b>Compal Electronics, Inc.</b>			
<b>Changed-List History</b>			
Size	Document Number	Rev	
	<b>BDQ11/LA-1601</b>	0.4	
Date:	星期二, 十二月 30, 2002	Sheet	53 of 56



# Version Change List (P. I. R. List) for Power Circuit

Item	Page#	Title	Date	Request Owner	Issue Description	Solution Description	Rev.
1	42	Power DC-IN	8/20/2002	Dell	Change PQ32, PR73, PR74, PR77 to NP	R318 change the value from 1240Ω to 1140Ω	X00
2	44	1.8V / 1.2V	8/29/2002	Compal	Change the control signal of 1.2V RUN from RUN_ON to RUNPWROK	Change netname from 4401_CLOCKRUN to 7705M_CLOCKRUN	X00
3	47	Vcc_core	9/03/2002	Dell	Banias update PBOOT voltage spec with 1.2V	Change PR755 to 16.5K and PR757 to 15K	X00
4	45	1.5V / 1.05V	9/05/2002	Compal	SUSPWROK_1P5V control signal detected glitch issue	Add PR767 and reserved PR742 to NP	X00
5	46	1.25V / 2.5V	9/05/2002	Compal	SUSPWROK_1P5V control signal detected glitch issue	Add PR768 and reserved PR605 to NP	X00
6	45	1.5V / 1.05V	9/26/2002	Dell	Add 0 ohm resistor at PU18 pin 15 and pin 16	Add PR769 and PR770 to 0Ω	X01
7	46	1.25V / 2.5V	9/26/2002	Dell	Add a 0 Ohm resistor at PU11 pin 15	Add PR771 to 0Ω	X01
8	45	1.5V / 1.05V	10/17/2002	Compal	Turn off have glitch because +3VSUS issue, so pull high to +5VSUS can improved	Add PR780 to 10KΩ	X01
9	45	1.5V / 1.05V	10/17/2002	Compal	Intersil Issue can solved by Fairchild solution Change the control signal of 1.05VSUS from RUNPWROK to SUSPWROK_5V	Add PR772, PR773 and change PC282 to 0.01U_0805 size	X01
10	44	1.8V / 1.2V	10/17/2002	Dell	Change the 1.8V RUN Regulator from CM3718 to MAX1927	Change +1.8V Regulator	X01
11	45	1.5V / 1.05V	10/17/2002	Dell	+1.5VSUS POWER GOOD ISSUE	change PL124 to 5.0U_20%_3.0A to 4.7U_20%_3.9A	X01
12	44-48	All Regulators	10/17/2002	Dell	Add test point for DELL testing	Add PR778, PR783, PR784, PR781, PR782, PR785, PR786 to NP for Test point	X01
13	49	Battery charger	10/23/2002	Dell	Fast Charger for short time and Cost-Down	Add P303 and Change PC202, PC203, PC204, PC211, PC212, PC213 to 10U_1210 and Delete PU15's circuit Change PR636 to 43.2K ohms for 65W Adpater plug in	X01
14	45	1.5V / 1.05V	10/23/2002	Dell	Change OCSETt and SEN Resistor	change PR735, PR736 to 75K ohms, Change PR727 to 330 ohms, Change PR728 to 634 ohms	X01
15	47	Vcc_core	10/28/2002	Dell	Cost-Down and change deepsleep offset	Change PR744, PC243, PC251, PC252, PR765 For adjusts slope and sleep offset PQ7, PQ11, PD24, PD27 to NP for Cost-Down	X01
16	47	Vcc_core	10/28/2002	Dell	EMI Broad band ISSUE	Add PC304 PC306 to 0.1U, Add PC305 PC307 to 2200P change PR747 PR756 to 3.3 ohms	X01
17	50	PWR_Selector	11/14/2002	Compal	Charger selector ISSUE	Add PR649, Del PD48, Change PD49 PD51 to B540C and Change PR657 PR662 to 33K	X02
18	42	Power DC-IN	11/20/2002	Dell	AC-IN Detect Issue	Change PR70 to 4.7K	X02
19	49	Battery charger	11/26/2002	Dell	Charger Current to 5.3A	Change PR627 to 28m ohms	X02

Compal Electronics, Inc.			
Title			
Changed-List History			
Size	Document Number	Rev	
	BDQ11/LA-1601	0.4	
Date:	星期五, 十二月 27, 2002	Sheet	55 of 56

# Version Change List (P. I. R. List) for Power Circuit

Item	Page#	Title	Date	Request Owner	Issue Description	Solution Description	Rev.
20	47	Vcc_core	11/29/2002	Compal	Delete V-core Cap for Cost-Down	Delete PC232 PC233 PC246 PC247 for Cost-Down	X02
21	50	PWR_Selector	12/16/2002	Dell	New Battery selector switch design to support secondary battery discharge before primary	Delete PQ72, PQ73 Change PQ86 to Dual-Mosfet ,Add PQ88 Mosfet Add PU19, PC308, PC309, U20B, PQ89, PQ90, PD57 And PR787, PR788, PR789, PR790, PR791, PR792, PR793 PR794, PR795@, PR796, PR797, PR798, PR799, PR800	X02
22	42	Power DC-IN	12/17/2002	Dell	EFT Issue and Dell request	Add PQ91, PD58 PR762 to depop	X02
23	42	Power DC-IN	12/18/2002	Compal	EFT Issue	Add PR801 to depop	X02
24	42	Power DC-IN	12/19/2002	Dell	Added PS_ID Pull-up	Add PR802 (4.7K_0402)@	X02
25	42	Power DC-IN	12/19/2002	Dell	Added +DC_IN 10K_0805 Pull-down to GND to solve potential adapter insertion secqurncing issue	Add PR803 (10K_0805)	X02
26	49	Chaqrger	12/20/2002	Dell	Added mΩ resistor in palleal with PR627 to support 6.0Amp maximun charging current	Add PR804 0.05mΩ_2512)	X02
27	49	Chaqrger	12/20/2002	Dell	Changed the Value of PR627 from 0.028 to 0.05	PR627 chande to 50m ohms	X02
28	44	1.8V / 1.2V	12/20/2002	Compal	Prevent 3.3ALW voltage droop during OTP & ThermTrip shutdown	Added PU20 (@)	X02
29	49	Chaqrger	12/20/2002	Dell	Changed the Value of PL120 from 6.0U to 5.6U	PL120 chande to 5.6UH_+-20%_8.8A	X02
30	42	Power DC-IN	12/20/2002	Dell	Prevent Bondi PS_ID Pin Issue	Add PR762 and PQ91@	X02

<b>Compal Electronics, Inc.</b>		
Title		
<b>Changed-List History-2</b>		
Size	Document Number	Rev
	<b>BDQ11/LA-1601</b>	0.4
Date:	星期五, 十二月 27, 2002	
	1	Sheet 56 of 56