

ICM MP Customer Care Information SI_1004.doc

«Name_LSO»
«Anrede» «Vorname» «Name»
«Zeile_1»
«Zeile_2»
«Zeile_3»
«Zeile_4»

Tel : «Telefon»
Fax : «Fax»

From (Name)
Dept.
Telephone
Fax

Henning Boll
ICM MP CCQ GRM R
+ 45 7219 5823
+ 49 7219 5835

Your Service Manager
Telephone
Our ref.
Date

«Anrede_SK» «Name_SK»
«Telefon_SK»
SI_1004.doc
February 13th, 2004

Subject: SX1 SWUP x 4 requires a program called lboot.

Dear «Anrede» «Name»

How to install the lboot program!



To use the parallel x4 SWUP on the SX1, the program "lboot_Install" must be installed on the PC, which will be used as the SWUP unit, and the function of it is to number each USB port as the Winswup needs to know what port to use for each load.

Please find the program on <https://communication-market.siemens.de>, select "Technique", "Software", "Device SW" and "SX1".

Download the program and install it to the PC. (The install process will be explained on screen).

Once the program is installed, it is not needed to run it again, unless the SWUP program is terminated, and one or more of the USB ports is used for other applications, and then later on the SWUP is restarted.

After the lboot installation, start the SWUP and on the initial run select parallel x4 update under "Options", then select "serial config" and set "USB 0 - 3", tick "Force USB port" and finally select "USB only".

When these settings are made, run the SWUP program and update the phones.

Please note: The selection "USB only" must be reset, if the program is terminated and restarted, all other settings will be saved in the program.

Best regards from ICM MP Customer Care.

sign. Andreas Worch
Customer Care O EMEA

sign. Hans-Juergen Burghart
Customer Care BA EMEA

Division:
Mobile Phones

Group Executive Management
Information and Communication Mobile:
Rudi Lamprecht, Group President
Joe Kaeser
Lothar Pauly

Postal address:
Siemens AG
ICM MP
Postfach 80 17 07
D-81617 München

Office address:
Siemens AG
Haidenauplatz 1
D-81667 München

Telephone +49 89 722 0